## Notification C Hazardous Waste Sit

**United States Environmental Protection** Agency Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compen-paper. Indicate the letter of the item sation, and Liability Act of 1980 and must which applies. be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of 810608

	OH		1 <i>3_3</i>			OHS-0	00-001-04
Ā	Person Required to Notify:  Enter the name and address of the person or organization required to notify.		DEN V	ZE NII	IE I ADC TNO		
			Name BEN VENUE LABS, INC.				
			Street 270 N	lort	hfield Road		
			City Bedfo	ord,		<sub>State</sub> Ohio	Zip Code 44146
В	Site Location:						
	Enter the common name (if known) and actual location of the site.		Name of Site BEN	VE	NUE LABS, INC.		
			270	) No	rthfield Road		
			Street	lfor	d, Cuyah	oga Ohio	44146
0	HD09/625749	City		County	State	Zip Code	
C	Person to Contact:						7
	Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.		Name (Last, First and		<del></del>	ey L., Ex. Vic	e Prex.
			Phone 216-232-3320				
D	Dates of Waste Handling:					······································	
	Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.		From (Year) 19	50	To (Year) 1976		
 E	Waste Type: Choose the option you prefer to complete						
	Option I: Select general waste types and so you do not know the general waste types or encouraged to describe the site in Item I—D  General Type of Waste: Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.  Source o Place an boxes.		sources, you are escription of Site.		Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).  Specific Type of Waste: EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site in		
	1. ₩ Organics	1. 🗆 Mii	ning		located.		
	2. ☑ Inorganics		nstruction	1	D007		
	3.  Solvents	3. ☐ Textiles		l			
	4. ☐ Pesticides	4. 🗆 Fertilizer		1			
	<ol><li>5. ☐ Heavy metals</li></ol>	<ol><li>□ Paper/Printing</li></ol>					
	6. ☐ Acids	<ol><li>6. ☐ Leather Tanning</li></ol>					
	7.  Bases	7. ☐ Iron/Steel Foundry					
	8. PCBs	8. 🖾 Chemical, General					
	9. ☐ Mixed Municipal Waste 10. ☐ Unknown		).   Plating/Polishing				
	— -		Military/Ammunition Electrical Conductors				
	12. □ Trar						
					ଯ −ର ଖା		
		15. □ Pho		}			
		16. □ Lab					
	17. □ Unl 18. □ Oth						
						US EPA RECORDS (	CENTER REGION 5
				:			14 14 <b>14 14 14 14 14 14 14 14 14 14 14 14 14 1</b>
			·				
	Form Approved OMB No. 2000-0138		·				109

Form Approved OMB No. 2000-0138

EPA Form 8900-1

JUN 1 2 198'

	Notification of Hazardous Waste Site	Side Two		b						
F	Waste Quantity:	Facility Type	Total Facility Was	te Amount						
	Place an X in the appropriate boxes to indicate the facility types found at the site.	1. □ Piles	cubic feet 67,50	0						
	In the "total facility waste amount" space		gallons							
	give the estimated combined quantity (volume) of hazardous wastes at the site	4. ☐ Tanks	Total Facility Area							
	using cubic feet or gallons.	<ol> <li>5. ☐ Impoundment</li> <li>6. ☐ Underground Injection</li> </ol>	square feet							
	In the "total facility area" space, give the estimated area size which the facilities	7.   Drums, Above Ground	acres (8.37)	8 A						
	occupy using square feet or acres.	8. Drums, Below Ground								
		9.  Other (Specify)								
G	Known, Suspected or Likely Releases to the Environment:									
	Place an X in the appropriate boxes to indicate any known, suspected,  or likely releases of wastes to the environment.									
	Note: Items Hand I are optional. Completin hazardous waste sites. Although completing			n locating and assessing						
Н	Sketch Map of Site Location: (Option	nal)								
	Sketch a map showing streets, highways, routes or other prominent landmarks near									
	the site. Place an X on the map to indicate the site location. Draw an arrow showing									
	the direction north. You may substitute a publishing map showing the site location.									
	Description of Site: (Optional) Solid wastes resulting from the neutralization with lime,									
	Describe the history and present conditions of the site. Give directions to									
	the site and describe any nearby wells, proporty in the early 1950 s. After about 1952 area was									
	information as how waste was disposed not used again until about 1960. At this time chemical									
	and where the waste came from. Provide manufacturing was entered into and solid wastes were any other information or comments which deposited until 1976 in this valley. At this time the									
	may help describe the site conditions.  deposited until 1976 in this valley. At this time the waste, neutralized with lime, consisted of magnesium									
	and calcium sulfate, and chromium III carbonates, and oxides. The process was monitored									
	from time to time for the presence of chromium VI and the amount was below the detectable limit.									
	There are no wells, springs or lakes within 1/2 mile of the area. The closest housing									
	is about 700 feet. Part of the wastes have been covered by land fill.									
	Organics could possibly be a very small amount in the waste estimated at less than									
	0.5%.									
J	Signature and Title:									
	The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address	Name BEN VENUE LABORATORIES	<ul> <li>■ Owner, Present</li> <li>□ Owner, Past</li> <li>□ Transporter</li> <li>□ Operator, Present</li> <li>□ Operator, Past</li> <li>□ Other</li> </ul>							
		Street 270 Northfield Road								
	in item A). For other persons providing	City Bedford, State O								
	notification, the signature is optional. Check the boxes which best describe the									
	relationship to the site of the person required to notify. If you are not required	Signature Stanley L. Mryan								
	to notify check "Other".	Stanley Morgan								

## Ben Venue Laboratories, Inc.

270 NORTHFIELD ROAD • P.O. BOX 46129 • BEDFORD, OHIO 44146 • 216 232-3320

June 8, 1981

U.S. EPA Region 5 Sites Notification Chicago, Ill. 60604

Gentlemen:

Enclosed is completed EPA Form 8900-1.

Yours truly,

BEN VENUE LABORATORIES, INC.

Stanley L. Morgan Vice President


SLM/ph

enclosure

JUN 1 2 1981

## Ben Venue Laboratories, Inc.

P O BOX 46129 270 NORTHFIELD ROAD BEDFORD, OHIO 44146



U.S. EPA Region 5 Sites Notification Chicago, Ill. 60604

Return recorpt requested